

SS50 Wall Panel


Installation - Monitor integration




Box Content




Needed in order to install




STEP 01Frame assembly fittings are only included for frame extensions



STEP 02
If needed, cut or drill hole in frame for cabling





STEP 03




STEP 04

Recommended maximum distance between holes is 40cm







STEP 06




STEP 07
Recommended maximum distance between holes is 40cm




STEP 08




STEP 09
Pass cabling through the previously cut hole




STEP 10




STEP 11Cut absorber to install monitor mount remembering to allow room for cabling.



STEP 12




STEP 13




STEP 14


When putting the canvas onto the frame, start by tucking in corners and then press along the edge, working gradually towards the centre of the panel.




STEP 15




STEP 16




STEP 17



STEP 18



STEP 19



More Info

https://akuart.com/product/ss50-wall-panel/

Need support? +45 27 50 82 90